DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES Office of Structural Materials

Quality Assurance and Source Inspection

Bay Area Branch 690 Walnut Ave.St. 150 Vallejo, CA 94592-1133 (707) 649-5453 (707) 649-5493



Contract #: 04-0120F4

Cty: SF/ALA Rte: 80 PM: 13.2/13.9

File #: 69.28

WELDING INSPECTION REPORT

Resident Engineer: Pursell, Gary **Report No:** WIR-009633 Address: 333 Burma Road **Date Inspected:** 06-Oct-2009

City: Oakland, CA 94607

OSM Arrival Time: 700 **Project Name:** SAS Superstructure **OSM Departure Time:** 1900 **Prime Contractor:** American Bridge/Fluor Enterprises, a JV

Contractor: Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China

CWI Name: Wan Wen Zhong, Chen Ying Xin.CWI Present: Yes No

Inspected CWI report: Yes N/A **Rod Oven in Use:** Yes No No N/A Yes N/A N/A **Electrode to specification:** No Weld Procedures Followed: Yes No N/A N/A **Qualified Welders:** Yes No **Verified Joint Fit-up:** Yes No N/A Yes No N/A **Approved Drawings:** Yes No **Approved WPS:** Yes No N/A

Delayed / Cancelled:

34-0006 **Bridge No: Component:** Tower

Summary of Items Observed:

On this day CALTRANS OSM Quality Assurance (QA) Inspector Umesh Gaikwad was present during the times noted above for observations relative to the fabrication of the SAS Superstructure being performed by Zhenhua Port Machinery Company (ZPMC) at Changxing Island in Shanghai, China. QA observed and/or found the following:

Bay 10 North Tower Lift 4 skin D stiffener welds

This QA inspector performed Magnetic Particle Testing (MT) of approximately 15% of the area previously tested and accepted by ZPMC Quality Control personnel. This QA Inspector generated an MT reports for this date. The members are identified as Tower Components. The weld designations reviewed are as follows.

NSD1-FDSA4-3D/D-1, 14, 15, 28, 29, 42, 56, 53A/B NSD1-FDSA4-3D/D-12, 13, 26, 27, 40, 41, 54, 55, 10, 11, 24, 25, 38, 39, 52, 51, 5, 6, 19, 20, 33, 34, 49, 50, 2, 3, 16, 17, 30, 31, 47, 48

This Quality Assurance (QA) Inspector observed the following work in progress:

Bay 10

FCAW welding of weld joint 3B located on NSD1-SPSA3-70. Welder is identified as 040261. ZPMC CWI is identified as Mr. Gong Liang Zhu.

WELDING INSPECTION REPORT

(Continued Page 2 of 2)

The welding variables recorded by QC appeared to comply with WPS-B-T-2231-Tc-U5-F.

SMAW welding of weld joint 7B located on ED1-A6001-8.

Welder is identified as 052930. ZPMC CWI is identified as Mr. Chen Ying Xin.

The welding variables recorded by QC appeared to comply with WPS-B-T-3212-Tc-U5b-1.

SMAW welding of weld joint 1A/B (Repair) located on ED1-A5007-14.

Welder is identified as 057258. ZPMC QC is identified as Mr. Yu Zhi Lai.

The welding variables recorded by QC appeared to comply with WPS-485-SMAW-1G(1F)-REPAIR.

SMAW welding of weld joint 12B located on ND1-A6002-7.

Welder is identified as 056364. ZPMC CWI is identified as Mr. Chen Ying Xin.

The welding variables recorded by QC appeared to comply with WPS-B-T-2212-Tc-U5b.

SAW welding of weld joint 8A located on ED1-STSA3-2-89M-2.

Welder is identified as 040252. ZPMC QC is identified as Mr. Yu Zhi Lai.

The welding variables recorded by QC appeared to comply with WPS-B-T-4221-B-U3c-S-1.

Unless otherwise noted, all work observed on this date appeared to generally comply with applicable contract documents.

Summary of Conversations:

Only general conversation was held between QA and QC concerning this project.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Serge Sinevod 134-8257-0045, who represents the Office of Structural Materials for your project.

Inspected By:	Gaikwad,Umesh	Quality Assurance Inspector
Reviewed By:	Clifford, William	QA Reviewer